Denver ATCT Introductions


Manager, Robert A. (Bob) Fletcher

Support Manager, Ron Olson



Denver ATCT (DEN) is providing this information to help you understand our role in the FAA's mission and to solicit feedback on the issue of similar call signs.







Operations



Denver International Airport (DIA) handled 618,870 operations last year.

That puts DIA over 6 million operations, without an accident, since opening on February 28, 1995



Air Traffic Control

Denver's Normal Arrival Rate is 152 Arrivals a Hour

Based on the availability of 4 Arrival Runways.

Due to our geographic location, traffic and weather patterns, multiple configurations are used daily to maximize the efficiency of the airport





SKW6628	2773 P16Ø3	KDEN	KDEN PLAIN4 GCK J28 ICT RZC MEM J41 VUZ KBHM	8
CRJ7/L		-	RZC HEH J41 VOZ KBIII	1672
406	37Ø			2 90
SKW6668 Z	65Ø4	KDEN	KDEN YELLOU BFF ABR FAR	340
CRJ2/L	P1604	1	KFAR	1547 -0 20
607	310			300
0	5113	KDEN	KDEN LUFSE V389 ADANE BRK	8
N.	P14Ø2		KCOS	403
\$10° 100°	120			
- 4	1446	KDEN	+YELLO4 CYS DDY BIL+	34R
CRJ2/L	P1412		KDEN YELLO4 CYS J13 BIL	23 95
267	340		KBIL	110
SKW657Ø	3733	KDEN	KDEN PLAIN4 GLD J182 ICT	8
CRJ7/L ✓	P1641		RZC MEM MSL DCU KHSV	1700
742	390			2093
SKW653Ø	2664	KDEN	KDEN YELLOH LAR BPI IDA	34L
CRJ7/L 5	P1710		KIDA	16
755	36Ø			345
SKW6695	6535	KDEN	KDEN PIKES4 ALS J13 RUTER	25
CRJ2/W	P1623		ELP KELP	30 25
656	340			
SKW6605	6547	KDEN	KDEN PLAIN4 HCT J128 OBH	341/10/6-
CRJ2/L 'S	P1612		J10 IOW KMLI	25 65
Ø3Ø	350			3
SKW6562	6524	KDEN,	KDEN YELLO4 BFF DPR DVL	23
CRJ2/L	P16Ø9	51	СҮМӨ	
143	35Ø	LE :		3-70360
SKW6662	655Ø	KDEN	KDEN YELLO4 HANKI ONL MCW	50
	P1612		MSN KMSN	25
	370			28 360

SKW6739 CRJ2/L Ø49	377Ø PØ312 32Ø	KDEN	KDEN PIKES4 ALS J13 RUTER ELP KELP	17L 1816
SKW6Ø39 CRJ2/L	1467 PØ328 32Ø	KDEN	KDEN ROCKIS DVC J146 FREDD HEC J6 PMD ARVIN1 KBFL	1757
SKW6561 CRJ2/L 847	Ø623 PØ325 34Ø	KDEN	J13 GTF KGTF	330
SKW6581 CRJ7/L 254	5177 PØ355 12Ø	KDEN	KDEN LUFSE V389 ADANE BRK KCOS	0356
SKW6633 CRJ7/L 175	2737 PØ325 38Ø	KDEN	KDEN PIKES4 ALS J13 TCS SSO ZONNA1 KTUS	5384
SKW6633 () \$\frac{1}{5} \cdot \frac{1}{5} \cdot	Ø637 PØ33Ø 32Ø	KDEN	KDEN PIKES4 ALS J13 TCS SSO ZONNA1 KTUS	174 1349

SkyWest 6050 and SkyWest 6605

SkyWest 6050 calls for taxi:

The Ground Controller grabs the wrong flight plan or strip. (SkyWest 6605)

The GroundController taxis SkyWest 6605. SkyWest 6050 answers.

Tower clears SkyWest 6605 for takeoff SkyWest 6050 answers.

No Clearance to SkyWest 6050 from ATC ever issued.







SkyWest 6563 and SkyWest 6562



- SkyWest 6563 Taxis and departs under SkyWest 6562 call sign.
- The aircraft's RADAR tag shows as SkyWest 6563.
- The controller believing that this is SkyWest 6562 changes his beacon code, there by changing the aircrafts destination.
- We vector SkyWest 6563 40 NM out of his way until the aircraft questions his call sign and routing.


SkyWest 6641 and SkyWest 6614

SkyWest 6614

(4Miles RADAR Separation Required behind UAL248)

UAL 248 (B757)

SkyWest 6641







SkyWest 6768 and SkyWest 6678



SkyWest 6768 calls for taxi.

 ATC uses the correct call sign but grabs the wrong flight plan.

 ATC uses the call sign SkyWest 6678.

SkyWest 6768 answers.





SkyWest 6728 and SkyWest 6720

Keylime 414

SkyWest 6720

SkyWest 6728








Denver ATCT maintains excellent working relationship with all of its stakeholders





Questions, Suggestions?

